

# TROUBLE SHOOTING



| Problem                  | Tap                            |   |   | Operating Conditions   |   |   |
|--------------------------|--------------------------------|---|---|--|---|---|
|                          | Specific Problem               | Selection   | Designed Spec.  | Regrinding   | Machine Used  | Tooling   |
| Oversize Pitch Diameter  | Incorrect tap selection        | ① Select tap of appropriate limit.<br>② Increase chamfer length.<br>③ Select con-eccentric relief tap.  | ① Reduce rake angle.<br>② Increase margin width of thread.<br>③ Correct relief angle of chamfer section.          |  |   |   |
|                          | Chip packing                   | ① Select POT/SFT/XPF/NRT/HRT.<br>② Select tap with oil hole.  | ① Reduce number of flutes to provide extra chip room.   |  |   |   |
|                          | Incorrect operating conditions |   |   |  | Adjust machine capacity (drive force) to appropriate level. | ① Use floating type tap holder.<br>② Avoid runout of spindle. |
|                          | Galling                        | ① Select surface-treatment (steam oxide or coating).<br>② Select tap with oil hole.   | ① Apply steam oxide treatment.<br>② Adjust rake angle to suit tapped material.<br>③ Shorten thread length of tap. |  |   |   |
|                          | Incorrect tap regrinding       |   |   | ① The land must be accurately indexed.<br>② Reduce run-out of chamfer section.<br>③ Make sure that rake angle and primary relief angle are not too large.<br>④ Make sure that land width is not excessively thin.<br>⑤ Remove burrs. |   |   |
| Undersize Pitch Diameter | Incorrect tap selection        | Select oversize tap.<br>(a) Tapping material: Materials with low over size margin, such as copper alloy, aluminum alloy and cast iron<br>(b) Shape of tapping material: Hollow materials and mild sheet steels with punched holes which have "a spring back" action after tapping | ① Adjust primary relief angle to appropriate level.<br>② Increase rake angle.                                     | Shorten regrinding intervals.  |   |   |
|                          | Damaged internal thread        |   |   |  |   |   |
|                          | Left-over chips                |   | Improve sharpness of cutting edges to prevent spare chips.  |  |   |   |
| Torn or rough Thread     | Incorrect tap selection        | Select tap with long chamfer length.  | ① Adjust rake angle to suit tapped material.<br>② Reduce margin width.<br>③ Shorten effective thread length.      |  |   |   |
|                          | Galling                        | ① Select tap with thread relief.<br>② Select surface-treatment (steam oxide or coating).<br>③ Select tap with oil hole.   | ① Reduce land width.<br>② Shorten effective thread length.  | ① The flutes must be accurately indexed.<br>② Reduce runout of rake angle.<br>③ Pay special attention to heat build up on the cutting edge.  |   |   |
|                          | Chip packing                   | Select spiral pointed or spiral fluted taps.  |   |  |   |   |

タップ TAPS  
 トラブルシューティング TROUBLE SHOOTING

# TROUBLE SHOOTING



| Operating Conditions  |   | Work Material |  |  | Other   |
|---|---|---------------|--|--|---|
| Tapping Conditions  | Cutting Lubricant   | Hardness      | Dimension  | Drill Hole   |   |
|   |   |               |  |  |   |
|   | Change lubricant type and lubricating method.   |               |  | ① Make drill hole diameter as large as possible.<br>② In the case of blind holes, make it as deep as possible. |   |
| ① Adjust tapping speed to appropriate level.<br>② Adjust feed speed to appropriate level to prevent torn or rough thread.<br>③ Use forced feed (lead feed) taper. |   |               |  | ① Prevent misalignment with drill hole.<br>② Chamfer entrance of the drilled hole.                             |   |
| ① Reduce tapping speed.   | Replace lubricant with one that has higher anti-galling properties.   |               |  |  |   |
|   |   |               |  |  |   |
|   |   |               | Select oversize tap.<br>(a) Tapping material: Materials with low over size margin, such as copper alloy, aluminum alloy and cast iron<br>(b) Shape of tapping material: Hollow materials and mild sheet steels with punched holes which have a 'spring back' action after tapping. |  |   |
| Adjust reverse speed to an appropriate level, to avoid damage at entrance of tapped thread on the way out of the hole.  |   |               |  |  |   |
|   |   |               |  |  | Before gauge check, be sure to remove chips completely. |
|   |   |               |  |  |   |
| Reduce tapping speed.   | ① Review lubricant type and lubricating supply method.<br>② Correct lubricant change/replenishment intervals.<br>③ Prevent entry of other oils such as operating oil.<br>④ Filtrate oil stored in tank. |               |  | Make drill hole diameter as large as possible.   | Remove chips generated in previous process.             |
| Make drill hole as large as possible.   | Review lubricant type and lubricating method.   |               |  | Make drill hole diameter as large as possible.   |   |

# TROUBLE SHOOTING



| Problem              | Tap                            |  |  | Operating Conditions  |                              |  |
|----------------------|--------------------------------|--|--|---|------------------------------|--|
|                      | Specific Problem               | Selection  | Designed Spec.   | Regrinding  | Machine Used                 | Tooling  |
| Torn or rough Thread | Incorrect operating conditions |  |  |   | Switch to pitch feed mode.   | ① Avoid runout of spindle.<br>② Use a floating type tap holder.                              |
|                      | Incorrect tap regrinding       |  |  | ① The land must be accurately indexed.<br>② Reduce run-out of chamfer section.<br>③ Make sure these are no worn-out areas.<br>④ Shorten regrinding intervals. |                              |  |
| Jagged Thread        | Incorrect tap selection        |  | ① Reduce rake angle.<br>② Reduce amount of thread relief.  | ① Make sure that land width is not excessively thin.<br>② Do not regrind flutes.  |                              | ① Use a floating type tap holder.<br>② Avoid runout of spindle.                              |
| Breakage             | Chip packing                   | Use spiral pointed, spiral fluted or forming taps  | ① Enlarge chip room<br>② Increase chamfer length.  |   |                              |  |
|                      | Galling                        | Select surface-treatment (steam oxide or coating).   |  | Make sure there are no worn-out areas.  |                              |  |
|                      | Excessive tapping torque       | Select tap with long chamfer length.   | ① Increase rake angle to improve cutting sharpness.<br>② Increase amount of thread relief and reduce land width to reduce friction torque. | ① Make sure there are no worn-out areas.<br>② Shorten regrinding intervals.   |                              |  |
|                      | Incorrect operating conditions |  |  |   | Avoid inconsistent feed rate | ① Use a tap holder that has torque adjustment function.<br>② Use a floating type tap holder. |
| Chipping             | Incorrect tap selection        |  | ① Reduce thread length.<br>② Change tool material.<br>③ Reduce hardness of the tap.<br>④ Increase chamfer length.                          | ① Make sure there are no worn-out areas.<br>② Make sure that land width is not excessively thin.  |                              |  |
|                      | Incorrect operating conditions |  |  |   | Avoid inconsistent feed rate | ① When tapping hole, do not reverse rotation suddenly.<br>② Use floating type tap holder.    |
| Excessive Wear       | Incorrect tap selection        | ① Select surface-treatment (steam oxide or coating).<br>② Select High-Speed Steel tap that contains high vanadium or powder metal tap. | If tapping material is hard, improve tool material or apply surface treatment.   | ① Make sure that rake angle is not too large.<br>② Avoid tapping burn.  |                              |  |
|                      | Incorrect operating conditions |  |  |   |                              |  |
| Galling              | Excessive frictional heat      |  | ① Increase amount of thread relief.<br>② Reduce land width.  |   |                              |  |

# TROUBLE SHOOTING



| Operating Conditions   |  | Work Material  |   |   | Other  |
|--|--|--|---|---|--|
| Tapping Conditions   | Cutting Lubricant  | Hardness   | Dimension   | Drill Hole  |  |
|  | Review lubricant type and lubricating method.  | Pay special attention to changes and variations in tapping material, hardness and structure. |   | ① Avoid misalignment and inclination from drilled hole.<br>② Avoid work hardening of the hole after tapping.  |  |
|  |  |  |   |   |  |
| Reduce tapping speed.  | Review lubricant type and lubricating method.  |  | ① Hold work material more securely.<br>② Pay special attention to thickness of work material. |   |  |
|  |  |  |   | ① Make hole for blind hole as deep as possible.<br>② Correct inclination of drilled hole.   | ① Remove chips collected in drilled hole and around tapping areas in previous process.<br>② Keep space for removal of chips. |
|  |  |  |   |   |  |
|  |  |  |   |   |  |
| ① Reduce tapping speed.<br>② Avoid misalignment between tap and drilled hole as well as inclination of drilled hole.<br>③ Avoid hitting bottom of the drilled hole with tap. |  | Pay special attention to changes and variations in tapping material, hardness and structure. |   | ① Avoid misalignment and inclination from drilled hole.<br>② Avoid work hardening of the hole after tapping.<br>③ Remove chips generated in previous process. |  |
|  |  |  |   |   |  |
| ① Reduce tapping speed.<br>② Avoid misalignment between tap and drilled hole as well as inclination of drilled hole.   | Use lubricant that has higher anti-galling properties.   | Pay special attention to changes and variations in tapping material, hardness and structure. |   | ① Avoid misalignment and inclination from drilled hole.<br>② Avoid work hardening of the hole after tapping.  |  |
|  |  |  |   |   |  |
| ① Reduce tapping speed.<br>② Avoid work hardening of the hole after tapping.   | Review lubricant type and lubricating method.  | Pay special attention to changes and variations in tapping material, hardness and structure. |   | ① Make hole as large as possible.<br>② In the case of a blind hole, make it as deep as possible.<br>③ Avoid work hardening of the hole after tapping.         |  |
| Reduce tapping speed.  | ① Review lubricant type and lubricating method.<br>② Correct lubricant change/replenishment intervals.<br>③ Prevent entry of other oils such as operating oil.<br>④ Filtrate oil stored in tank. |  |   |   |  |